

10/10/2007

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
LAURENS County					
AM PM FOOD STORE	PETRO	UST	BLWM		Site ID #10284. RBCA Classification 4AA8. Awaiting Funding.
BAILEY PROPERTY	PETRO	UST	BLWM		Site ID #15325. RBCA Classification 4BC5. Inactive.
BLALOCK TEXTILE MILL	PETRO, VOC	UNK	BOW		Monitored natural attenuation.
BRAGG CONVENIENCE STORE	PETRO	UST	BLWM		Site ID #15476. RBCA Classification 2BB3. Monitored Natural Attenuation (MNA).
BUCKS AUTO SALES	PETRO	UST	BLWM		Site ID #09837. RBCA Classification 2AA4. Active Corrective Action.
CALDWELL SERVICE STATION	PETRO	UST	BLWM		Site ID #11291. RBCA Classification 3BA5. Inactive.
CAROLINA COMMERCIAL HEAT TREATING LLC	PETRO	UST	BLWM		Site ID #05608. RBCA Classification 5A5. Inactive.
CAROLINA GAS & GRILL	PETRO	UST	BLWM		Site ID #05666. RBCA Classification 3BF5. Inactive.
CHILDRESS CASH & CARRY	PETRO	UST	BLWM		Site ID #11279. RBCA Classification 2BB8. Awaiting Funding.
CITY OF CLINTON LANDFILL	VOC	LF	BLWM		In monitoring phase. Low level of vinyl chloride in MW-2A. Permit # 301002-1201.
CLINTON MILLS-PLANTS 1 AND 2	VOC, METALS	OTHER, UNK	BLWM	SCD980079479	BLWM File # 52085. In assessment and monitoring phases. Plume is discharging to creek/storm water network.
CLINTON TIRE SERVICE INC	PETRO	UST	BLWM		Site ID #15629. RBCA Classification 4AA5. Inactive.
CMI INDUSTRIES LANDFILL	VOC	LF	BLWM		In monitoring phase. Requested Appendix II sampling. VOC's in MW-2 and MW-3. Permit # DWP-019.
COMMUNITY QUICK SHOP	PETRO	UST	BLWM		Site ID #11694. RBCA Classification 3BA8. Awaiting Funding.
CONTINENTAL MACHINE CO	PETRO	UST	BLWM		Site ID #15813. RBCA Classification 2BA8. Awaiting Funding.
COPELAND GULF	PETRO	UST	BLWM		Site ID #05698. RBCA Classification 3BA5. Inactive.
COPELANDS SERVICE STATION INC	PETRO	UST	BLWM		Site ID #05694. RBCA Classification 3BA2. Free Product Recovery only.
CORNER STOP 55	PETRO	UST	BLWM		Site ID #05700. RBCA Classification 4AA8. Awaiting Funding.
CRYOVAC DUMP SITE	METALS	LF	BLWM	SCD980844021	In monitoring phase. Removal of waste has been accomplished.
DEBS QUICK STOP	PETRO	UST	BLWM		Site ID #15736. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti
DELOACH GROCERY	PETRO	UST	BLWM		Site ID #16096. RBCA Classification 2BB5. Inactive.
E Z SERVE 8170	PETRO	UST	BLWM		Site ID #10496. RBCA Classification 3AA7. Approved Monitored Natural Attenuation (MNA Awaiti

10/10/2007

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
ENMARK 160	PETRO	UST	BLWM		Site ID #05669. RBCA Classification 3BA5. Inactive.
ENMARK 310	PETRO	UST	BLWM		Site ID #05664. RBCA Classification 3BA5. Inactive.
ERNESTINE STARNES PROPERTY	PETRO	UST	BLWM		Site ID #15460. RBCA Classification 2BB8. Awaiting Funding.
FARMERS TEXACO	PETRO	UST	BLWM		Site ID #11293. RBCA Classification 3BF3. Monitored Natural Attenuation (MNA).
FORMER KING OIL FACILITY	PETRO	UST	BLWM		Site ID #18888. RBCA Classification 5A7. Approved Monitored Natural Attenuation (MNA) Awaiti
FREDS GULF BP	PETRO	UST	BLWM		Site ID #14183. RBCA Classification 3BD3. Monitored Natural Attenuation (MNA).
FULLERS GULF	PETRO	UST	BLWM		Site ID #05707. RBCA Classification 4AA6. Contacted.
GATE PETROLEUM 306	PETRO	UST	BLWM		Site ID #05712. RBCA Classification 4AA8. Awaiting Funding.
GRAY COURT EXXON	PETRO	UST	BLWM		Site ID #05701. RBCA Classification 3BA3. Monitored Natural Attenuation (MNA).
GREENWOOD MILLS COTTON INSULATION	PETRO	UST	BLWM		Site ID #05697. RBCA Classification 5A5. Inactive.
GURPREET ENTERPRISES INC	PETRO	UST	BLWM		Site ID #11885. RBCA Classification 3BA4. Active Corrective Action.
H D PAYNE & COMPANY	PETRO	UST	BLWM		Site ID #11256. RBCA Classification 3BF5. Inactive.
HIGHWAY 221 SOUTH	PETRO	UST	BLWM		Site ID #11290. RBCA Classification 2BA2. Free Product Recovery only.
HILL OIL CO	PETRO	UST	BLWM		Site ID #05621. RBCA Classification 3BA1. Conducting Investigation/Risk Assessment.
HOLLIDAY GROCERY	PETRO	UST	BLWM		Site ID #11285. RBCA Classification 2BB8. Awaiting Funding.
HOME STORE 1	PETRO	UST	BLWM		Site ID #05702. RBCA Classification 3BA2. Free Product Recovery only.
HWY 14 QUICK STOP	PETRO	UST	BLWM		Site ID #17615. RBCA Classification 4BC1. Conducting Investigation/Risk Assessment.
JIM & DONNAS TRADING POST	PETRO	UST	BLWM		Site ID #18333. RBCA Classification 2BB8. Awaiting Funding.
JOE KELLYS TROPHY SHOP	PETRO	UST	BLWM		Site ID #10292. RBCA Classification 2BB5. Inactive.
KMO 122	PETRO	UST	BLWM		Site ID #10300. RBCA Classification 4AA1. Conducting Investigation/Risk Assessment.
LAURENS CERAMTEC	VOC	PPL, LF	BOW		In assessment phase. Remediation options being evaluated for plant two area. Water well has been impacted. Contaminant discharging to an unnamed tributary and Reedy Fork.

10/10/2007

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
LAURENS COMMISSION OF PUBLIC WORKS	PETRO	UST	BLWM		Site ID #12847. RBCA Classification 4AA1. Conducting Investigation/Risk Assessment.
LAURENS COUNTY LANDFILL	VOC	LF	BLWM		In assessment phase. Plume is discharging to on-site unnamed tributary. Below MCL detection of one VOC (cis-1,2 Dichloroethene) in a grab sample from creek. Permit # 301001-1101.
LAURENS PATROL FACILITY	PETRO	UST	BLWM		Site ID #05591. RBCA Classification 4BC5. Inactive.
LIL CRICKET 251	PETRO	UST	BLWM		Site ID #05671. RBCA Classification 5A5. Inactive.
MOONS LANDING	PETRO	UST	BLWM		Site ID #11276. RBCA Classification 2AA8. Awaiting Funding.
PIEDMONT PETROLEUM CORP	PETRO	UST	BLWM		Site ID #05675. RBCA Classification 2BA4. Active Corrective Action.
QUICK FOOD MART #5	PETRO	UST	BLWM		Site ID #05668. RBCA Classification 2BA8. Awaiting Funding.
QUICK POINT LAURENS	PETRO	UST	BLWM		Site ID #10019. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaits
RAMAGES TEXACO	PETRO	UST	BLWM		Site ID #11264. RBCA Classification 3BF5. Inactive.
RANDY SIMS EXXON	PETRO	UST	BLWM		Site ID #05663. RBCA Classification 2BB6. Contacted.
ROPER'S WEE SHOPPE	PETRO	UST	BLWM		Site ID #15134. RBCA Classification 3BA5. Inactive.
RUBYS FOOD STORE	PETRO	UST	BLWM		Site ID #05670. RBCA Classification 3BA5. Inactive.
SAV WAY 207	PETRO	UST	BLWM		Site ID #12466. RBCA Classification 4AA5. Inactive.
SHOP N SAVE	PETRO	UST	BLWM		Site ID #05713. RBCA Classification 4AA8. Awaiting Funding.
SHORT STOP	PETRO	UST	BLWM		Site ID #05678. RBCA Classification 3BA8. Awaiting Funding.
SHORT STOP OF CLINTON INC	PETRO	UST	BLWM		Site ID #18363. RBCA Classification 4AA5. Inactive.
SPEEDWAY 620	PETRO	UST	BLWM		Site ID #05647. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaits
SPEEDY FOOD 1	PETRO	UST	BLWM		Site ID #10375. RBCA Classification 4BC1. Conducting Investigation/Risk Assessment.
TIMKEN (FORMER TORRINGTON CLINTON BEARINGS PLANT)	VOC	UST, PPL	BLWM	SCD003345683	In assessment, monitoring, and remediation phases. Hazardous waste permit for post-closure care issued December 1996. Groundwater contamination off-site.
WELBORNS FISHING SUPPLY	PETRO	UST	BLWM		Site ID #13930. RBCA Classification 2BB3. Monitored Natural Attenuation (MNA).
WILSON COUNTRY MARKET	PETRO	UST	BLWM		Site ID #11259. RBCA Classification 3BF5. Inactive.

10/10/2007

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
YOUNGS GULF STATION	PETRO	UST	BLWM		Site ID #05695. RBCA Classification 4AA1. Conducting Investigation/Risk Assessment.
Total for LAURENS		65			